

Geological Hazard Division News

On April 30-May 1, the team consists of IPG Geological Hazard Division, MOP-DRBFC, and CDRS team conducted the 6th Inclinometer Monitorization at A05 road (Sta: 1+300) along Aituto Area, Ainaro Municipality.

The Monitorization of inclinometer is to identify the landslide movement which displaced along the A05 road slope in Aituto. This Inclinometer monitoring will be continuing every month until the end of the year. The result of the Inclinometer data will be used later for Slope Stability Analysis and Study in the area.



Figure: Inclinometer Monitoring and Data Collection between IPG, Geological Hazard Division, MOP-DRBFC, and CDRS Team